



## Internal Services Department

*Facilities Management Division · Fleet Management Division · Landscaping & Grounds Division*

REPLACEMENT OF UPS AT CUMBERLAND COUNTY DEPARTMENT OF PUBLIC HEALTH

### ADDENDUM III – QUESTIONS & ANSWERS

(Answers in red)

1. What is the continuous current rating for the input breaker feeding the UPS?  
The input breaker is a SquareD HJA36150 with an 80% continuous current rating.
2. Is there any way to confirm the length of conductor inside the bottom feed cabinet?  
No, the cabinet would need to be disassembled to determine how much excess conductor is available.

Fleet Management  
426 Mayview Street  
Fayetteville, NC 28306  
910 321-6963

Facilities Management  
420 Mayview Street  
Fayetteville, NC 28306  
910-678-7699

Landscaping & Grounds  
807 Grove Street  
Fayetteville, NC 28302  
910-678-7560