Questions for RFP #251-25-385 – Lighting Equipment Replacement – Leesville Road High School

Reference	Vendor Question	Answers				
	THE DUE DATE FOR THE SUBMISSIONS HAS BEEN EXTENDED BY ONE WEEK. EMAIL BIDS ARE NOW DUE BY 5/20/25 AT 12:00 NOON.					
	What comprises a complete and working system?	For this project, the new Johnson Systems equipment should be fully installed and set up to work together to control the dimmer racks. Everything required to integrate the new equipment into the existing system should be included in the bid to create a "complete and working system". If there is existing equipment that is not replaced as part of this bid, and that equipment does not work, it would not be incumbent upon the bidder to fix it to provide a "complete and working system".The model numbers on the riser drawing for the Presidor Wall Stations are correct. The Bill of Materials is as follows:QTYMANUFACTURERMODELDESCRIPTION				o the bid hat is hot be
	It appears there are conflicting model numbers in the bid.					correct.
		4	Johnson Systems	EDI-60	Dimmer Processor	
		6	Johnson Systems	PWS-20P-RETRO-B	Control Station	
		2	Johnson Systems	PWS-20P-RETRO-W	Control Station	
		2	Johnson Systems	PA-4A1	Adapter Plate	
	Is there an installation timeline?	Bidders are asked to include in their bids a proposed installation time for how much time would be needed in the space. In addition, if vendors have specific availability regarding when work could begin, please share that. WCPSS realizes that each vendor's availability may change after they submit the bid.Vendors are welcome to submit multiple proposals. The second proposal could be with Paradigm as an alternative to Johnson Systems. However, the dimmer racks will not be able to be changed out in the scope of this project.If there is a credit for the return of the old modules that reduces the cost to the district, vendors should note the amount of that credit in their proposal.				ific
	Can vendors propose Paradigm instead?					
	If Johnson systems will offer a credit for the return of the old modules, how should vendors indicate that?					